



J. H. FLETCHER & CO. Box 2187 – Huntington, WV 25722-2187 – 304/525-7811 – FAX 304/525-4025

IMPORTANT RECALL NOTICE

INFORMATION BULLETIN NO. 62

TO: ALL OWNERS, MAINTENANCE SUPERVISORS AND REBUILDERS OF J. H. FLETCHER

& CO. ROOF BOLTERS AND MRS UNITS

FROM: RISK MANAGEMENT DEPARTMENT

J. H. FLETCHER & CO.

DATE: JUNE 1996

SUBJ: RECALL PROGRAM FOR THE NULL 1200-A AND 1200-2 HEADLIGHT/METER

ASSEMBLIES

J. H. Fletcher & Co. has been informed that Null's Machine & Manufacturing Inc. is performing a recall of its headlight/ meter assemblies. J. H. Fletcher has been utilizing this component on roof bolters and MRS units since 1990, and our records indicate that we have used 379. Our part number is 34803, and the component drawing EM-56 is enclosed. If this component was installed on your equipment, there should be a copy of this headlight assembly in your serial number specific parts book, which will enable you to determine if your equipment is affected.

The following are excerpts from the notification received from Null's Machine & Manufacturing Inc.:

"This is a potential discrepancy notice on the model 1200-1 AL and the 1200-2 AL headlight/meter assemblies. The potential discrepancy is the flame path surface on the housing (see attached drawing). This flame path surface must be at least .500" wide to conform to MSHA standards. A flame path under the required .500" could fail to prevent the transmission of a flame resulting in a mine explosion.

Please check the flame path distance as shown in the attached drawing immediately. Use the provided inspection form to record the results of your inspection.

All assemblies that conform to MSHA standards are to be stamped using a letter "R" that is at least 1/4" high. The stamp will be placed on the mounting foot of the assembly as shown on the attached drawing. Please be advised that upon completion of the recall program any 1200 headlight/meter assembly that does not have the "R" stamp will be considered out of compliance by the MSHA inspectors."

Information Bulletin No. 62 Subject: Null's Machine & Manufacturing Inc. Recall June 1996 Page 2

We are requesting that you take immediate steps to inspect your equipment and return the enclosed form and all non-conforming assemblies to J. H. Fletcher & Co. for FREE replacement.

If you have any questions, please contact our Risk Management Department at 304/525-7811, ext. 240.

INSPECTION FORM FOR 1200-1, 1200-2 HEADLIGHT/METER ASSEMBLIES

TOTAL NUMBER OF 1200 HEADLIGHT/ME QUANTITY:	TER ASSEMBLIES INSPECTED:
SERIAL NUMBER(S) AND MODEL(S) OF M	1ACHINE(S) INSPECTED:
Serial Number	Model
TOTAL NUMBER OF 1200 HEADLIGHT/ME	TER ASSEMBLIES ACCEPTED:
QUANTITY:	
NOTE: Stamp a minimum 1/4" high letter "R drawing.	t" on the foot of the assembly as shown in the attached
TOTAL NUMBER OF 1200 HEADLIGHT/ME	TER ASSEMBLIES REJECTED:
QUANTITY:	
NOTE: All rejected 1200 Headlight/Meter as and returned to J. H. Fletcher & Co.	ssemblies are to be immediately removed from service for FREE replacement.
COMPANY NAME, ADDRESS AND TELEPH	HONE NUMBER:
DATE OF INSPECTION:	
COMPANY REPRESENTATIVE:	





